

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: April 9, 2021

TO: Mitsubishi Motors US Service and Parts Managers

RE: Photo Required Condition (PRC) for Valve Cover leaks related to the Valve Cover Gasket P/N 1035A583 on 4B1 Series Engines (4B11, 4B11T, 4B12)

TIN: TIN-21-13-001

AFFECTED VEHICLES: 2008-2017 Lancer (non-Turbo), 2008-2013 Outlander, 2018-2020 Outlander PHEV, and 2011-2021 Outlander Sport

PURPOSE

When replacing the Valve Cover Gasket due to a customer concern of oil leaking, dealers are requested to complete the following steps prior to performing the repair and submitting a warranty claim.

NOTE: If the required documentation is not included in the PRC entry, then the claim is subject to debit.

1. Enter clear and focused photos of the leak at the Valve Cover Gasket, the VIN, and current Odometer reading into the Photo Required Condition & Pre-Approval Center (PRC).

When creating the PRC submission, select "MMNA REQUESTED PHOTOS/DOCS" from the "Optional/Requested" list under the Repair Type.

2. Once the required photos have been entered into the PRC, replace the Valve Cover Gasket and the Valve Cover.
3. Retain the replaced Valve Cover Gasket and Valve Cover for collection.

NOTE: Photos should be posted on the PRC BEFORE entering the related Warranty claim.

Please select appropriate Labor Operation Code(s) from the list below:

Model	Labor Operation Code
2011-2021 Outlander Sport	11131010
2018-2020 Outlander PHEV	11131010
2008-2013 Outlander	11131010
2008-2017 Lancer	11131010