



SERVICE CAMPAIGN

CAMPAIGN BULLETIN

Expiration Notification – Drive Belt Tensioner Bolts

Reference: **PB072**
Date: **March 25, 2021**

Attention: Dealer Principal, Sales, Service & Parts Managers

Affected Models/Years:	Affected Population:	Dealer Inventory:	SERVICE COMM Expiration date:
2008 Altima Sedan (L32) Equipped with 4 Cylinder 2.5L Engine	N/A	N/A	March 25, 2021

****** Campaign Summary******

In 2008, Nissan launched a Voluntary Service Campaign on certain 2008 Altima (L32) vehicles, equipped with 4-cylinder 2.5L engine, to re-torque the engine accessory drive belt tensioner bolts to specification. During manufacturing, the engine accessory drive belt tensioner bolts may not have been torqued to specification. This may affect performance of certain engine accessories on the vehicle, including the air conditioning compressor, alternator and the water pump.

Parts specified for this campaign are no longer available through Nissan. This customer service campaign and customer reimbursement for these repairs are no longer available.

****** What Dealers Should Do ******

1. Service Comm will deactivate **PB072** on any unrepaired VINs on **March 25, 2021**. No further dealer action is required.

****** Release Schedule ******

Repair	<ul style="list-style-type: none"> • Campaign bulletin NTB08-051 has been updated to reflect expiration of this voluntary service campaign. Please discard older copies.
Owner Notification	<ul style="list-style-type: none"> • No expiration notices are being sent to customers.

NISSAN NORTH AMERICA, INC.

Aftersales DIVISION