Technical Bulletin



SERVICE BULLETIN

 Classification:
 Reference:
 Date:

 KS16-020A
 NTB16-047A
 March 15, 2021

2014-2016 ROGUE; INTELLIGENT KEY AND/OR ELECTRICAL ISSUES AFTER INSTALLATION OF AFTERMARKET REMOTE START

This bulletin has been amended. See AMENDMENT HISTORY on the last page.

Discard all previous versions of this bulletin.

APPLIED VEHICLES: 2014-2016 Roque (T32)

SERVICE INFORMATION

- Changes or modifications to the vehicle electrical system (including the installation of <u>aftermarket</u> remote-start devices) may affect the proper operation of the vehicle electrical systems.
- Installation of <u>aftermarket remote-start devices</u> may cause Intelligent Keys to not register, buttons in the Intelligent Key to not operate, and other electrical system related issues.
- <u>The new vehicle limited warranty</u> does not cover damage or failures resulting from or caused by alteration, tampering, or installation of non-Nissan approved accessories or components, including aftermarket remote-start devices.
- Refer to the <u>Assurance Product Resource Manual</u> and read the specific model year Warranty Information Booklet for complete details regarding the new vehicle limited warranty.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 28, 2016	NTB16-047	Original bulletin published
March 15, 2021	NTB16-047A	Classification Number updated

2/2 NTB16-047A