



Engine	Part	Part Number	Quantity
1.5L Turbo: DNKA	Oil Filter	04E 115 561 H 04E 115 561 AC	1
	VW 508 00 Use synthetic oil SAE 0W-20	4.3L (4.5 qt.)	1
	Drain Plug w/Gasket	902 889 01	1
	Air Filter	04E 129 620 5QM 129 629 B	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Dust and Pollen Filter	5Q0 819 669	1
	Front Wiper Blade (Left)	2GJ 955 425	1
	Front Wiper Blade (Right)	2GJ 955 426	1
	Rear Wiper Blade (370 mm)	2GJ 955 427	1
	Battery (Amp. Req. Vary)	1S0 915 105 A 000 915 105 EB 5K0 915 105 D 000 915 105 DD 5GM 915 105 N	1

*VIN Required

2021	Engine Code		Torque Spec
Oil drain plug Torque	1.5L	DNKA	30 Nm
Wheel hub bolt Torque	1.5L	DNKA	140 Nm

5/18/2021

2022 Taos Service Reminder Reset

Resetting the service interval display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

Vehicles with a digital instrument cluster: The service interval display can only be reset through the service menu.

Do **not** reset the service interval display between service intervals or incorrect information will be displayed.

If the oil change service was manually reset, the service interval display then also switches to a fixed service interval, even on vehicles with **flexible oil change service**.



The service message disappears after a few seconds when the engine is running or when the **OK** button on the multi-function steering wheel is pressed.



If the 12 V vehicle battery in a vehicle with flexible service was disconnected for an extended period, the time for the next service cannot be calculated. Therefore, the service interval displays may show incorrect calculations. If this is the case, follow the maximum permissible maintenance intervals.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.