

SSM 49807 - 2020-2021 Corsair - Distorted View When Looking At The Exterior Mirror Glass

Some 2020-2021 Corsair vehicles may exhibit a distorted view when looking at the exterior mirror glass. This may be due to the mirror glass not being fully seated into all retaining tabs and not the glass itself. Verify that the exterior mirror glass is fully seated into all of the retaining tabs before attempting any further repairs. Refer to Workshop Manual (WSM), Section 501-09.

APPLICABLE VEHICLES

2020 - 2021 CAR: TF CX483N CORSAIR