

DTNA Solutions > Service Solutions > Western Star
> SS 702-WST2021 49X Hood Fender Marker Lamp

SS 702-WST2021 49X Hood Fender Marker Lamp

Applicable Vehicles

49X Builds

Symptoms

Hood fender marker lamps inoperable, retaining water, corrosion.

Issue

Marker lamp design may allow water to collect internally.

Solution

Replace marker lamps A66-10531-004 with A66-10531-006 and locking nut 23-14767-000.

Labels :

49X

Add tags

Attachments



5/25/2021

SS /02-WS12021 49X Hood Fender Marker Lamp - DINA Solutions



0 Kudos

Comment

