

DTNA Solutions > Service Solutions > Western Star  
> SS 703-WST2021 49X Wheel Cut and Fender Interferen...

# SS 703-WST2021 49X Wheel Cut and Fender Interference

## **Applicable Vehicles**

49X vehicles built with certain 425 size front steer tires.

## **Symptoms**

Wheel cut on front steer tires interfere with inner fender.

## **Issue**

wheel cut may cause contact between tire and inner fender.

## **Solution**

Replace inner fender per crossover below:

A22-75451-000 to A22-75451-004

A22-75451-001 to A22-75451-005

A22-75451-002 to A22-75451-006

A22-75451-003 to A22-75451-007

Labels :

49X

Add tags



0 Kudos

## Comment