


	VOLUME 3	GROUP Body	MODEL 2009 Rio (4 door)
		NUMBER 042	DATE November 2008

TECHNICAL SERVICE BULLETIN

SUBJECT:
SERVICE ACTION: 2009 RIO FUEL DOOR ADJUSTMENT (SA004)

This bulletin provides information related to adjusting the open door detent for the fuel door assembly. On vehicles produced from 7/12/2008 to 9/10/2008 the fuel door may not stay locked in the open position during refueling. This procedure involves adjusting the detent height and allow the detent to lock in place as designed.



Fuel Filler Door Adjustment

***NOTICE**

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer request to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service>Warranty Coverage>Warranty Coverage Inquiry>Campaign Information). Not Completed Recall/Service Action reports are available on WebDCS (Consumer Affairs>Not Completed Recall Recall VIN>Select Report).

The issue number is SA004.

File Under: Body

-
- Circulate To: General Manager Service Manager Parts Manager
 Service Advisor(s) Technician(s) Body Shop Manager Fleet Repair

SUBJECT:

SERVICE ACTION: 2009 RIO FUEL DOOR ADJUSTMENT (SA004)

7. Check to make sure the fuel door is centered and adjusted properly before releasing vehicle back into service.



AFFECTED PRODUCTION RANGE:

2009 MY Rio produced from 7/12/2008 through 9/10/2008.

WARRANTY INFORMATION:

Warranty Coverage: Basic (5/60)

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Time	Related Parts	Qty
V	69510 1G200	0	N95	C24	SA004-Fuel Door Adjustment	080046R0	0.2 M/H	N/A	0

***NOTICE**

VIN inquiry for this repair is provided for tracking purposes only. Kia retailers should reference SA004 when accessing their Dealer Communications System (DCS).