



GROUP
Transmission

MODEL
2010MY Soul
w/MT

NUMBER
029


DATE
October 2009

TECHNICAL SERVICE BULLETIN

SUBJECT:

SERVICE ACTION: SOUL MANUAL TRANSMISSION SHIFT SKIRT
(SA015)

This bulletin provides information related to Soul models produced from 1/8/2009 ~ 9/13/2009. Some Soul customers with manual transaxles may complain the vehicle maybe difficult to get into first (1st) gear when coming to a stop. To repair this concern replace the transmission gear shifter lower skirt, complete shifter assembly replacement is NOT necessary.



Shifter Assembly – Lower Skirt Replacement

File Under: Transmission

Circulate To: General Manager Service Manager Parts Manager
 Service Advisor(s) Technician(s) Body Shop Manager Fleet Repair


SUBJECT:

SERVICE ACTION: SOUL MANUAL TRANSMISSION SHIFT KNOB (SA015)

AFFECTED PRODUCTION RANGE:

2010 Soul (AM) vehicles produced from January 8, 2009 ~ September 13, 2009

PARTS INFORMATION:

Part Name	Part Number	Photo
Lower skirt – TGS Lever	43713 2K100QQK	

WARRANTY INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Time	Related Parts	Qty
V	43700 2K100WK	0	N94	C38	SA015 - M/T Shift Lever Skirt Replace	090050R0	0.2	43713 2K100QQK	1

***NOTICE**

VIN Inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA015 when accessing their Dealer Communications System (DCS).