

GROUP Chassis	MODEL 2009MY Rondo (UN)
NUMBER <b>021</b>	DATE February 2010

### TECHNICAL SERVICE BULLETIN

SUBJECT:

SERVICE ACTION: 2009MY RONDO (UN) FRONT STRUT UPPER NUT RETIGHTENING (SA028)

This bulletin provides information relating to some 2009MY Rondo (UN) vehicles built April 9, 2009 ~ July 16, 2009. While driving on an uneven road, some experience abnormal noise originating from the upper area of the front structure wrench and the 6" torque adapter tool to retighten the front structure locking) on both sides to specified torque specification.



## \*NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer request to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service>Warranty Coverage> Warranty Coverage Inquiry>Campaign Information). Not Completed Recall/Service Action reports are available on WebDCS (Consumer Affairs>Not Completed Recall Recall VIN>Select Report).

The issue number is **SA028**.

File Under: Chassis

Circulate To: X General Manager X Service Manager X Parts Manager

X Service Advisor(s) Technician(s) X Body Shop Manager X Fleet Repair

SUBJECT:

# SERVICE ACTION: 2009MY RONDO (HN) FRONT STRUT UPPER NUT RETIGHTENING (SA028)

#### AFFECTED PRODUCTION RANGE:

MODELS	PRODUCTION DATE RANGE				
2009MY Rondo (UN)	April 9, 2009 ~ July 16, 2009				

#### **REQUIRED SST:**

- 6" Torque Adapter Tool
- Torque Wrench

6" Torque Adapter 06700-20100	Torque Wrench				

#### WARRANTY CLAIM INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Time	Replacement Part No.	Qty
V	54659 1F100	N/A	N29	C29	(SA 028) Front Strut Nut Retighten	090070R0	0.3 M/H	N/A	N/A



VIN Inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA028 when accessing the WebDCS system.