

Subject: VEHICLE KEY OR REMOTE START WILL NOT PROGRAM	M-Tips No.: MT-002/21
	Last Issued : 05/07/2021

BULLETIN NOTES

This M-Tip supersedes the previously issued article(s) listed below: The changes are noted in Red.

Previous M-Tip(s):	Date(s) Issued:
MT-014/15	01/17/2017

APPLICABLE MODEL(S)/VINS

2010-2021 Mazda3	2009-2021 Mazda6	2020-2021 CX-30	2016-2021 MX-5
2013-2021 CX-5	2016-2021 CX-3	2007-2021 CX-9	

DESCRIPTION

When programming a key or installing a Genuine Mazda Accessory Remote Engine Start system, you may encounter programming difficulty. This may be caused by a customer installed aftermarket decorative trim and/or cover on the START/STOP ENGINE button.

The aftermarket accessory may create electrical interference, which may interfere with programming.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.
To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com . All contributions become property of MNAO, which assumes permission to publish them without further consideration.

