

REMOTE DIAGNOSTICS REPAIR INSTRUCTIONS



DTC: See DTC's Below

Bulletin: RD21-027

Date: May 10, 2021

Description: Hybrid/EV Driveline Reactivity System

Applies to: Electric Vehicles

For Spanish click here: [ESPAÑOL](#)

****THESE REPAIRS ARE THE MOST LIKELY FIX FOR THE IDENTIFIED FAULT(S). IF THIS DOES NOT FIX THE ISSUE, TECH TOOL WILL NEED TO BE USED FOR MORE DETAILED DIAGNOSTICS****

General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P1003-93	Hybrid/EV Driveline Reactivity System - No Operation	N/A	N/A
P1003-97	Hybrid/EV Driveline Reactivity System - Component or System Operation Obstructed or Blocked		
P1003-9A	Hybrid/EV Driveline Reactivity System - Component or System Operating Conditions		

Required Parts

Part Number	Description	Quantity
Tech Tool diagnostics will point to defective component		

Repair Instructions

- This is an informational DTC that is logged due to Hybrid/EV This is an information DTC logged due to another component fluctuating current
- The DTC will go inactive when all the DTCs related to This is an information DTC logged due to another component are fixed

****If there are no issues found from the checks above or the code(s) continue to log after the steps above are followed, normal diagnostic steps should be followed in Premium Tech Tool.****

Additional Resources

These repairs are the most likely fix for the identified fault. If this does not fix the issue, Tech Tool will need to be used for more detailed diagnostics. If filing a warranty claim, please include the ASIST case number.

Labor Code	
N/A	N/A
Causal Part	N/A



DTC: Por favor de consultar los códigos de error(es) abajo

Boletín: RD21-027

Descripción: Sistema híbrido/EV de reactividad de la línea de motriz

Fecha: 10 de mayo, 2021

Se aplica a: Vehículos eléctricos

Para inglés, haga clic aquí: **ENGLISH**

****ESTAS REPARACIONES SON LA SOLUCIÓN MÁS PROBABLE PARA LOS FALLOS IDENTIFICADOS. SI ESTO NO SOLUCIONA EL PROBLEMA, UTILIZE TECH TOOL PARA DIAGNÓSTICOS MÁS DETALLADOS****

Información general

Estas instrucciones de reparación están destinadas a solucionar el siguiente error(s):

DTC	Descripción	Posible causa	Posibles síntomas (observables)
P1003-93	Sistema híbrido/ EV de reactividad de la línea de motriz- Sin operación	N/A	N/A
P1003-97	Sistema híbrido/ EV de reactividad de la línea de motriz- Operación del componente o del sistema obstruida o bloqueada		
P1003-9A	Sistema híbrido/ EV de reactividad de la línea de motriz- Condiciones de funcionamiento de los componentes o del sistema		

Piezas requeridas

Número de pieza	Descripción	Cantidad
Los diagnósticos de Tech Tool apuntarán a componentes defectuosos		

Instrucciones de reparación

- Este es un DTC informativo que se registra debido al híbrido/EV Este es un DTC de la información registrado debido a otra corriente fluctuante del componente
- El DTC entrará inactivo cuando se corrijen todos los DTC relacionados con Esta es una información DTC registrada debido a otro componente

Recursos adicionales

Estas reparaciones son la solución más probable para el error identificado. Si esto no soluciona el problema, Tech Tool tendrá que usarse para diagnósticos más detallados. Si presenta una reclamación de garantía, incluya el número de caso ASIST.

Código laboral	
N/A	N/A
Pieza Adecuada	
N/A	N/A