

**Subject: Engineering Information - Tick and/or Ping Type Noise Heard From the Propeller Shaft During Acceleration and/or Braking**

*This PI has been revised to end the need for information from the field. Please discard PIE0615.*

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019	<b>Vehicles Built After the Following Dates:</b> <ul style="list-style-type: none"> <li>● Ft. Wayne: June 11, 2020</li> <li>● Silao: March 17, 2020</li> </ul>		-	-
	Silverado 1500	2020	2021				
GMC	Sierra 1500 (New Model)	2019	2019				
	Sierra 1500	2020	2021				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released March 08, 2021 Revised April 26, 2021 – Ended the need for further information from the field