

Subject: Engineering Information – Service Power Steering Message Illuminated on Driver Information Center (DIC), DTC C005' 58 Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

This EI has been revised to end the need for information from the field. Please discard PIE0620A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020	2021	—	—	—	—
Chevrolet	Trailblazer (VIN M)	2021		—	—	—	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released March 19, 2021 April 01, 2021 – Updated the Correction. April 15, 2021 – Ended the need for further information from the field.