 HYUNDAI Technical Service Bulletin	GROUP Body Electrical	NUMBER 21-BE-003H-1
	DATE May, 2021	MODEL(S) Azera (HG) Elantra GT (GD) Veloster (FS) Veracruz (EN) Santa Fe (CM/CMa) Genesis (BH) Equus (VI)
SUBJECT: CLOCK SPRING WARRANTY EXTENSION (TXXJ)		



This TSB supersedes TSB# 21-BE-003H to provide clarification of warranty coverage in the description and add additional models including Genesis (BH), Equus (VI), Santa Fe (CM/CMa), and Veracruz (EN).

Description: The warranty coverage for the clock spring has been extended to 15 years with unlimited mileage from the date of original retail delivery or date of first use, whichever occurs first. This warranty coverage applies to both the original and subsequent owners. Refer to the warranty and service parts information outlined in this bulletin whenever clock spring replacement is required.



Applicable Vehicles:	
Model:	Production Date:
2012-2014 Azera (HG)	NOV. 29, 2011 To APR. 01, 2014
2013-2014 Elantra GT (GD)	MAY 02, 2012 To APR. 28, 2014
2012-2014 Veloster (FS)	JUL. 02, 2011 To MAY 12, 2014
2007-2012 Veracruz (EN)	DEC. 26, 2006 To JUL. 24, 2012
2007-2012 Santa Fe (CM/CMa)	APR. 19, 2006 To JUL. 03, 2012
2009-2014 Genesis (BH)	APR. 30, 2008 To JAN. 17, 2014
2011-2013 Equus (VI)	JUL. 13, 2010 to NOV. 24, 2012

SUBJECT:**CLOCK SPRING WARRANTY EXTENSION (TXXJ)****Parts Information:**

PART NAME	PART IMAGE	MODEL	PREVIOUS	AFTER	QTY
Clock Spring		Elantra GT (GD)	93490-1W120	93490-A4120FFF	1
		Azera (HG)	93490-3V120	93490-A4120FFF	1
			93490-3V125	93490-A4120FFF	1
		Veloster (FS)	93490-3V110	93490-B2110FFF	1
		Veracruz (EN)	93490-3J100	93490-3J100FFF	1
		Santa Fe (CM/CMa)	93490-2B300	93490-2B300FFF	1
		Genesis (BH)	93490-3M000	93490-3M000FFF	1
			93490-3M500	93490-3M500FFF	1
Equus (VI)	93490-3N000	93490-3N000FFF	1		
Steering Lock Nut		EN, BH, VI, HG, GD, FS	N/A	56195-2F000	1 per vehicle
		CM/CMa		13467-14001	

Warranty Information:

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
All	10D008R0	CLOCK SPRING DIAGNOSIS ONLY	0.3M/H	Please see causal part listed in below replacement op code for your applicable model.	I3R	ZZ3
Genesis (BH)	10D008R1	CLOCK SPRING DIAGNOSIS AND REPLACEMENT	0.7M/H	93490-3M000FFF	I3R	ZZ3
Veloster (FS)	10D008R2		0.7M/H	93490-B2110FFF	I3R	ZZ3
Santa Fe (CM/CMa)	10D008R3		0.6M/H	93490-2B300FFF	I3R	ZZ3
Veracruz (EN)	10D008R4		0.6M/H	93490-3J100FFF	I3R	ZZ3
Azera (HG)	10D008R5		0.6M/H	93490-A4120FFF	I3R	ZZ3
Elantra GT (GD)	10D008R6		0.5M/H	93490-A4120FFF	I3R	ZZ3
Equus (VI)	10D008R7		0.5M/H	93490-3N000FFF	I3R	ZZ3

NOTE 1: Submit Claim on Campaign Claim Entry Screen

NOTE 2: If a part that is not covered by this TSB is found in need of replacement while performing TXXJ, and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.