



Preliminary Information

PIT5812A Grind Noise From Brakes

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2021	All	All	All	All
Chevrolet	Equinox	2021	All	All	All	All
GMC	Canyon	2021	All	All	All	All
GMC	Terrain	2021	All	All	All	All

Involved Region or Country:	North America
Condition:	Grinding noise on brake apply cold that dissipates after a few stops.
Cause:	New no copper pad composition.

Engineering is investigating this concern and working towards a resolution. Replacing pads will not eliminate this concern for the long term. Deglazing the pads and rotors does help the concern in the short term. This PI will be removed and a bulletin released when the field fix is available.

Version History

Version	2.0
Modified	02/02/2021 - Created on. 05/10/2021 - Revised to add models.



GENERAL MOTORS