



Preliminary Information

PIT5842 Service Power Steering Message Illuminated On Driver Information Center (DIC)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2020 - 2022	All	All	All	All
Chevrolet	Trailblazer	2021 - 2022	All	All	All	All

Involved Region or Country	North America
Condition	<p>A customer may comment on the Service Power Steering message illuminated on Driver Information Center (DIC). There will be no drivability or steering related issues other than the message.</p> <p>Upon a GDS2 scan check DTC C0051 SYM58 (Steering Wheel Angle Sensor Performance) will be stored in the K43 Power Steering Control Module.</p>
Cause	Engineering is currently working on a permanent solution.

Correction:

If there are no drivability or steering issues as mentioned above, then clear out the DTC.

Please communicate to the customer that we apologize for this inconvenience.

Engineering is working on a permanent solution. As more information becomes available this PI will be updated or advanced to a bulletin.

Warranty Information

Version History

Version	1
Modified	05/17/20221 - Created on.



GENERAL MOTORS