

Technical Journal

TITLE:

Ghost DTC set, VCU1-U210782

| REF NO: TJ 35944.1.0 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | | | |
|-------------------------|---------------------------------------|--------------------------------------|-------------------------|--|--|
| 3 US 7 | PARTNER: '510 Volvo Car USA | ISSUE DATE: 2021-04-29 | STATUS DATE: 2021-05-04 | | |
| FUNC GROUP: 3640 | FUNC DESC: Electrical item | Page 1 of 2 | | | |

[&]quot;Right first time in Time"

DESCRIPTION:

VCU1 = Vehicle Computational Unit #1

In some cases, the DTC VCU1-U210782, "Collision Mitigation by breaking, Bus Signal" may be set in VCU1, usually after a software update, with no customer symptoms present. This is due to the new VCU1 software that was released earlier this year.

CSC Customer Symptom Codes

| Code | Description |
|------|--|
| 1C | Service/repair/Administrative and Factory scheduled maintenance |
| 3L | Technician information/Repair information/Not for warranty use |
| 2V | Technician information/Software/Vehicle communication/Not for warranty use |

DTC Diagnostic Trouble Codes

| Control Module | Code | Fault Type | | |
|-----------------------|---------|--------------|--|--|
| VCU1 | U210782 | Intermittent | | |

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | ('hassis range | Struc Week Range |
|------|-----|-------------|-------|------|------|-------|------------|-------|-----------------|---------------------|
| 224 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 225 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 227 | | | | | | | 2020-2022 | | - | 201920-202146 |

Technical Journal 35944.1.0



| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|-------------|-------|------|------|-------|------------|-------|---------------|---------------------|
| 235 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 236 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 238 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 246 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 256 | | | | | | | 2020-2022 | | - | 201920-202146 |
| 536 | | | | | | | 2021-2022 | | - | 202020-202146 |

SERVICE:

If DTC VCU1-U210782 is set after a software upgrade, it can be ignored as it does not affect any of the functions in the car.

No action needs to be taken to erase or fault trace this DTC.

The car can leave the workshop with this DTC set.

In case of an actual fault, this DTC is set in combination with other VCU1-communication DTC's and an error message will be displayed in the DIM (Driver Information Module).

New software to correct this DTC to be set is planned to be released later this year.

Warranty claim info:

N/A

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3640.

Page 2 of 2 2021-05-04