



91-20-01 - MIB3 Radio DTC B200045 Control Module Faulty

Release date: 6/7/2021

Condition

| Applicable Vehicles | | | | | | |
|--------------------------------------------------------------------------|------|-----------|-------------|----------------|--------------|---------|
| Model(s) | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To | PR Code |
| Arteon, Atlas, Atlas Cross Sport, Golf/GTI, Jetta, Tiguan | 2021 | All | All | All | All | 8AR |
| Taos | 2022 | All | All | All | All | 8AR |

| Revision Table | | | |
|-----------------|----------------|----------------|------------------------------|
| Instance Number | Published Date | Version Number | Reason For Update |
| 2061690/4 | 6/7/20 | 91-20-01 | Include an additional model. |
| 2061690/1 | 12/16/20 | 91-20-01 | Original publication. |

During diagnosis, DTC B200045 – Control Module Faulty may be present in the **-J794-** Information Electronics Module (Address Word 5F).

Technical Background

The presence of this DTC does not in any way affect the operation of the Infotainment system and should be ignored. **No repair attempts are recommended for this DTC.**

Production Solution

Not applicable.

Service

NA.

Warranty

Information only.



91-20-01 - MIB3 Radio DTC B200045 Control Module Faulty

Release date: 6/7/2021

Required Parts and Tools

| Tool Description | Tool No: |
|-----------------------------------|----------------------------------------------------------------------------|
| Midtronics Battery Tester/Charger | GRX3000VAS or MTRMSP0702 battery maintainer/charger |
| VAS Diagnostic Tool | VAS 6150/X & VAS 6160/X and - ODIS Service with: current online updates |

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.