



MB Sprinter Chassis – Bolt that connects the brake pedal to its bearing block could come loose.

Jayco - Body Builder	
Bulletin Type:	<u>Chassis Advisory Notice</u>
Jayco CAN #:	21-006
Publication Date:	June, 2021
Make:	Jayco Entegra Class C Motorhomes
Model(s) Model Yr(s):	2020 Melbourne 2020-21 Melbourne Prestige 2020-21 Qwest

Mercedes- Benz- Chassis Builder	
Chassis Bulletin:	Safety Recall
Chassis SA #:	21V-152
Publication Date:	June, 2021
Chassis Model:	MB – 3500 Sprinter
Chassis Model Year:	2019-2020
Component/Area:	Brake pedal

Chassis Incident:	The retaining washer on the bolt that connects the brake pedal to its bearing block could come loose. If the retaining washer were to come loose, over time it could detach from the bolt, and in the worst case and with ongoing use of the brake pedal, the bolt might separate from the bearing block on one side. If this were to occur, the brake lamp switch could become continuously activated even when the brake pedal is not pressed. If the brake lamps are continuously illuminated, it would not be possible for following traffic to determine the braking intention of the vehicle, which could increase the risk of a crash.
Affected Chassis:	Model Year 2019-2020 Mercedes-Benz Sprinter vehicles.
Mercedes-Benz Contact	https://www.mbvans.com/en/home 1-800-367-6372