



2021 Jetta, Jetta GLI



Engine	Part	Part Number	Quantity
1.4L DGXA, DJXA	Oil Filter	04E 115 561 H	1
	VW 508 00 Use synthetic oil SAE 0W-20	N/A	4.0L (4.2qt)
	Drain Plug Gasket	N 013 815 8	1
	Air Filter	5QM 129 620 B	1

Engine	Part	Part Number	Quantity
2.0L DKFA	Oil Filter	06L 115 562 B	1
	VW 508 00 Use synthetic oil SAE 0W-20	N/A	5.7L (6.0qt)
	Drain Plug w/Gasket	06L 103 801 D	1
	Air Filter	5Q0 129 620	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter (20K Only)	5Q0 819 669	1
	Driver's Wiper Blade (Left)	17B 955 425 A	1
	Passenger's Wiper Blade (Right)	17B 955 426 A	1
	Battery	5K0 915 105 D*	1

*VIN Required

2021	Engine Code		Torque Spec
Oil drain plug Torque	1.4L	DGXA, DJXA	30 Nm
	2.0L	DKFA	
Wheel hub bolt Torque	1.4L	DGXA	140 Nm
	2.0L	DKFA	

Revised 6/23/2021



2021 Jetta, Jetta GLI



2021 Jetta/Jetta GLI Service Reminder Reset

Resetting the service interval display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

Vehicles with analog instrument cluster:

1. Switch the ignition off.
2. Press and hold the **0.0** button in the instrument cluster.
3. Switch the ignition back on.
4. Release the **0.0** button when one of the following messages appears in the instrument cluster display: **Reset oil change service?** or **Reset inspection service?**
5. Press the **0.0** button in the instrument cluster to confirm.

Vehicles with a digital instrument cluster:

The service interval display can only be reset through the service menu.

Do **not** reset the service interval display between service intervals; or incorrect information will be displayed.

If the oil change service was manually reset, the service interval display then also switches to a fixed service interval, even on vehicles with **flexible oil change service**.



The service message will go out after a few seconds if the engine is running or if you acknowledge the message on the instrument cluster.



If the 12 V vehicle battery in a vehicle with flexible service was disconnected for an extended period, the time for the next service cannot be calculated. Therefore, the service interval displays may show incorrect calculations. If this is the case, follow the maximum permissible maintenance intervals.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.