

Subject:

EXTERIOR TRIM HEAT DAMAGE

M-Tips No.: MT-003/21

Last Issued : 06/01/2021

BULLETIN NOTES

This M-Tip supersedes the previously issued M-Tip listed below. The changes are noted in **Red** text.

Previous Service Alert	Date(s) Issued
MT-038/16	01/11/2017


APPLICABLE MODEL(S)/VINS

CX-3 2016 - 2021	Mazda2 2011 - 2021	RX-8 2004-2011
CX-5 2013 - 2021	Mazda3 2004 - 2021	
CX-7 2007 - 2012	Mazda5 2006 - 2017	
CX-9 2007 - 2021	Mazda6 2003 -2021	
CX-30 2020- 2021	MX-5 2006 - 2021	

DESCRIPTION

Some vehicles may experience exterior trim heat damage when parked near a glass building. This may be caused by the sun's reflection.

If a building creates enough of a curve with a series of flat windows, which act like mirrors, the reflections all converge at one point, focusing and concentrating the light onto the street below.

**Warranty Compliance Note:**

Vehicle repairs for this concern are not covered under Mazda's warranty policy.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com. All contributions become property of MNAO, which assumes permission to publish them without further consideration.