

DTNA Solutions > Service Solutions > Western Star
> SS 709-WST 2021 Fuel Sending Unit Connector Loose

SS 709-WST 2021 Fuel Sending Unit Connector Loose

Applicable Vehicles

49X builds.

Symptoms


Fuel distribution from tank may be affected.

Issue

Fuel sending connector detached/unplugged.

Solution

Tie strap fuel sending unit on the plug locking tab to prevent disconnection.



Labels :

49X

Add tags

👍 0 Kudos

Comment