

VOLVO TRUCKS DEALER BULLETIN



To: General Managers, Service Managers, Service Technicians, Warranty Managers
From: Volvo Trucks – Service
Date: June 30, 2021
Subject: Service Literature Published and Released in June, 2021
Bulletin: SLV21-006

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TOOL BULLETIN

BULLETIN #	TITLE	COMMENTS
	None Issued	

FIELD SERVICE BULLETIN

BULLETIN #	TITLE	COMMENTS
FSB 213-002v2	Exhaust Rocker Compression Brake Piston, Repair	Revision

SERVICE PROGRAM

BULLETIN #	TITLE	COMMENTS
	None Issued	

RECALLS

BULLETIN #	TITLE	COMMENTS
SRA-V21-02	Safety Recall Alert RVXX2102, Proprietary Hubcap	New
C6627	Safety Recall RVXX2102, Proprietary Hubcap	New

VOLVO TRUCKS DEALER BULLETIN



(CBR) CASE BASED REASONING

NEW SOLUTIONS

SOLUTION #	TITLE
CBR-2110	Chassis Alteration Request
CBR-2027	Reoccurring Diagnostic Trouble Code (DTC) P245700 Following EGR Cooler Cleaning Or Replacement
CBR-2128	Engine Control Module (EMS) Software Information - Improvement List (Change Log), June 2021 – US21+OBD2021 Emissions ONLY
CBR-2129	Oil Leak At Turbo Oil Supply Line And Fitting Connection - 11L
CBR-2106	Volvo Chassis - Unable To Program VECU: Error Code 155; Possible EMS DTC U000188 CAN Communication Backbone 2 Net
CBR-2119	DTC U012100 - Poor Connection At The X209 Ground Junction
CBR-2121	Eaton Endurant Shift Pad Corrected Schematic
CBR-2112	Programming Failure - Chassis With Cummins Engine And An Allison Transmission
CBR-2130	Volvo Chassis - I-See Module Diagnostic Information - Models VNL, VNR, VNM

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-2107	Diagnostic Trouble Codes (DTC) P205B64 - Reductant Tank Temperature Sensor Circuit Range/Performance - US17+OBD16 Emissions And Newer	Update to step #4 changed from 50% to ensure the tank is adequately filled.
CBR-2114	3rd Party NOx Sensor Identification	Added updated pictures.
CBR-2023	Volvo Chassis - Model VNR With RH Side Fairing Only - Heat/Splash Shield Loose, Possible DTC P204800 And/Or P204713	Added new Containment instructions (split washer).
CBR-459	Volvo Chassis - Diagnostic Trouble Code (DTC) P0471 Illuminating The Malfunction Indicator Lamp (MIL) - Turbo Compound Generation I	Revised formatting, added correct information for screenshot solution, corrected categories, completed tags.
CBR-175	AMT-F With Crawler Gears - During Gearbox Removal From The AMT: Input Shaft Slips Out Of The Gearbox Or Becomes Loose In The Gearbox	Added background statement to the body of the article.
CBR-2086	Volvo Chassis - Model VNL, VNR - DEF Fill Door Loose, Vibrating, Broken - Repair Information	Added drill bit diameter and rivet part number. Corrected categories and tags.
CBR-15	Diagnostic Trouble Codes (DTC) For The Engine Pre-Heat Relay: Supplementary Instructions	Updated the categories and added Volvo models.