

# AMB5 Stop delivery/Recall Campaign - Reprogramming power electronics

Version 4

## **AMB5 Stop delivery/Recall Campaign - Reprogramming power electronics**

---

### **Update 7/1/21**

Please note that the campaign has been updated to a Stop Delivery/Recall Campaign. This updates serves as Pre-Information of the upcoming Safety Recall for sold cars.

A full VIN list of all affected cars is not yet available.

---

---

### **Update 6/25/21**

Please note that initial information is available to remedy over 90% of vehicles affected by Stop Delivery AMB5. This measure is valid for vehicles that are assigned to work scope 5.

All necessary information to repair and claim work involved are available in the attached Technical Information.

The VIN list has been updated to highlight vehicles with and without scope 5.

Vehicles may be delivered and RDR'd upon completion and clearance of the respective warranty claim for AMB5.

---

## IMPORTANT REMINDER

**IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.**

---

### Overview

Due to a software issue that has since been corrected, the software designed to continuously monitor end-to-end communication between the safety-related ECUs in the vehicle can, in certain instances, incorrectly and sporadically detect a potentially faulty communication, set an error memory entry and trigger a shutdown of the power train, resulting in loss of motive power. To help prevent this from occurring, high-voltage power electronics must be reprogrammed with updated software.

Model type	Taycan (Y1A) Taycan Cross Turismo (Y1B)
Model year	2020-2021
Number of affected vehicles	1,424*

\*Note that additional vehicles in current production may be added. These VINs will be show in the PPN post and will be reflected in the relevant systems.

### Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain. Further use is not permitted. Test drives are to be omitted.

## Test instructions and remedial measures

Work Instructions are estimated to be available next week (Calendar week 26).

## Subsequent procedure

Please inform all relevant dealer staff of this notice. Note that the Stop Delivery is active in PCSS and vehicles are blocked in PVMS with code AMB5.

[AMB5 Stop Delivery VIN List\\_Scope 5.XLSX](#) ⓘ

**96.2 KB**

(309 views)

[AMB5 Technical Information Scope 5.pdf](#) ⓘ

**339.0 KB**

(845 views)

Created by [Ryan Cooney](#) on Jun 24, 2021 10:15 PM. Last modified by [Mitchell Grasser](#) on Jul 1, 2021 5:40 PM.

2691 Views [Report Abuse](#)

Categories: Taycan, Recalls, Stop Sale

Tags : [stop delivery](#), [taycan](#), [my2020](#), [my 2021](#), [y1a](#); [y1b](#), [vehicle blocking](#), [amb5](#)

### Content and Topics

Your Groups >

Your Content >

Your Places >

### Personal

Edit Profile >

Change Password >

### Manage

Admin Console >

PPN Administration >

### Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [011](#)