

CAMPAIGN LAUNCH STATUS

H348 AND N572 - N583 AND H355



OWNER NOTIFIED SERVICE ACTIONS H348 AND N572

AFFECTED MODELS	21MY F-PACE 21-22MY RR/RRS/EVOQUE/DISCOVERY/VELAR/DEFENDER WITH P6 ENGINE
VOLUME AFFECTED	676 USA 106 CAN
REPAIR	Certain models within the affected model and VIN ranges may have been built with superchargers with an internal circuit board that could short circuit leading to a MIL and reduced engine performance. All affected vehicles will require a replacement e-supercharger
REPAIR TIME	Between 1.6 and 2.7 hrs dependent on model +DIDO
TARGET CAMPAIGN LAUNCH	June 4 th 2021
Notes	c. 110 units are in Retailer Inventory

ONP SERVICE ACTION - N583 and H355 MISSING ACTIVITY KEY

AFFECTED MODELS	21-22MY Defender, Discovery, RR Evoque and Discovery Sport, Range Rover, Range Rover Sport, F-PACE
CURRENT VOLUME AFFECTED	523 USA 48 CAN * MORE VEHICLES TO BE ADDED
REPAIR	Due to the Global semi-conductor chip shortage, some Land Rover and Jaguar vehicles will be shipped to market without an activity key. The campaign bulletin advises retailers of this situation and that later this year when parts are available the campaign will be published with a repair process to add the key.
REPAIR TIME	N/A
CAMPAIGN LAUNCH	May 20th, 2021
Notes	Confirm Vehicles are included by checking the Warranty Portal. Vehicles may be sold with this open campaign. First affected unit wholesale by May 28 th . Repair bulletin will be published later in 2021 when key supply is resumed and customers are mailed..