

Roof Opening Panel Inoperative	20 – 21MY Defender
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A customer may report that the roof opening panel does not operate or that the sunblind lost 'One Touch' operation. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- This may be caused by the roof opening panel motor losing calibration. <p><u>Status:</u></p> <ul style="list-style-type: none">- SSM 75429 is going through sign-off to address this concern by providing repair guidance to calibrate the roof opening panel motor.- The roof opening panel motor should not be replaced for this concern.	