

Air Conditioning System Inoperative (3 Zone Only)	21MY Defender
<p>Customer Voice:</p> <ul style="list-style-type: none"> - A customer may report that the air conditioning system does not cool properly. <p>Technical Description:</p> <ul style="list-style-type: none"> - This may be caused by an excessive amount of refrigerant installed during production. This applies to vehicles with 3 zone climate control systems only. <p>Status:</p> <ul style="list-style-type: none"> - SSM 75418 has been published to address this concern by providing repair guidance to recover the refrigerant and recharging the system to the correct refrigerant level. - The VIN range of the potentially affected vehicles is provided in the SSM. 	