# **TECHNICAL TOPICS BODY/CHASSIS**





## Front Seat Lower Level Parts

### Customer Voice:

A customer may report a rattle noise coming from the front seat area.

## Technical Description:

If a rattle is heard from the seat cushion pan, a service kit has been released to allow the repair to be performed in the vehicle without separating the seat cushion from the seat squab.

#### Status:

- The repair method has been added to the Workshop Manual, Section 501-10 Seating > General Procedures > Front Row Seat Pan Bracket.
- Service kit part number LR156907 and T2R68777 are now available and used be used to conduct a lower level repair when required.

15 – 19MY RR Evoque 17MY – Onwards Range Rover, RR Sport, F-TYPE, XF, X.









