

TECHNICAL TOPICS

BODY/CHASSIS



Rear Lamp Condensation	15MY – Onwards Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport, Defender, F-PACE, I-PACE, XF, XE, XJ, F-TYPE
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> – A customer may express a concern that there is moisture inside one of the rear lamp assemblies. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> – Under certain atmospheric conditions, it is normal to have slight misting/ condensation inside the lamp assembly. – Most misting/ condensation clears within 60 minutes of continuous lamp on time. <p><u>Status:</u></p> <ul style="list-style-type: none"> – The Rear lamp Diagnosis and Testing section in the Workshop Manual has been updated to provide guidance on testing and what is normal and what is a fault. – Standing water or streaking water droplets is not acceptable and requires lamp replacement. – Photographic evidence is required to be attach to the repair order for all claims of rear lamp condensation, pre and post drying process. 	 

