

**SERVICE BULLETIN**

Classification:

EL10-038H

Reference:

NTB10-124H

Date:

June 7, 2021

EXTENDED STORAGE SWITCH AND BCM TRANSIT MODE

APPLIED VEHICLES: 2013 – 2017 Frontier (D40)
2013 – 2017 GT-R (R35)
2013 – 2017 NV 1500/2500/3500/Passenger (F80)

This bulletin is no longer active.

Please discard previous versions of NTB10-124.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 19, 2010	NTB10-124	Original bulletin published
November 5, 2010	NTB10-124A	Bulletin cancelled
December 16, 2010	NTB10-124B	Bulletin republished
March 15, 2011	NTB10-124C	APPLIED VEHICLES and pages 2, 4, and 5 revised
September 6, 2011	NTB10-124D	Changes made throughout
November 21, 2011	NTB10-124E	Adoption Date Table revised
February 10, 2012	NTB10-124F	Adoption Date Table revised
April 10, 2017	NTB10-124G	Changes made throughout
June 7, 2021	NTB10-124H	Bulletin no longer active

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.