

Service Bulletin

Bulletin No.: 21-NA-079

Date: May, 2021

TECHNICAL

Subject: Pop Noise Heard During Seat Travel and/or Inadequate Seat Rearward Travel

Brand:	Model:	Model Year:		Build Breakpoint Date:			Additional
		from	to	from	to	Engine:	Options (RPOs):
Chevrolet	Silverado 1500 Silverado 2500/3500	2021	2021	SOP	November 20, 2020	All	AFE
GMC	Sierra 1500 Sierra 2500/3500						

Involved Region or Country	North America, Middle East, Israel, Chile, Paraguay, Uruguay, Thailand, Australia and New Zealand.	
Condition	Some customers may comment on hearing a pop noise during seat travel and/or inadequate seat rearward travel.	
Cause	The cause of the condition may be an incorrect right hand seat track.	
Correction	Replace the lower seat frame assembly by following the procedure below.	

Service Procedure

If you encounter a vehicle with the above concern, replace the front seat cushion frame. Refer to *Front Seat Cushion Frame Replacement* in SI.

Parts Information

Use the VIN and refer to the GM Electronic Parts Catalog (EPC) to determine the proper part number to order.

Causal Part	Description	Part Number	Qty
Х	Frame, F/Seat	13526540	1
	Cush (Manual)	13526541	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7020180	Front Seat Cushion Frame Replacement	Use Published Labor Operation Time

Version	1
Modified	Released May 03, 2021

