

DTNA Solutions > Service Solutions > Freightliner
> SS 3082-FTL2021 P4 New Cascadia Fuel Sending Uni...

SS 3082-FTL2021 P4 New Cascadia Fuel Sending Unit Connector Loose

Applicable Vehicles

All P4 Vehicles

Symptoms

Fuel gauge reads empty.

Issue

Fuel sending connector detached/unplugged.

Solution

Tie strap fuel sending unit on the plug locking tab to prevent disconnection (See Figure 1)




Figure 1

Labels :

- Electrical
- New Cascadia

Add tags

 0 Kudos

Comment