

Due to obsolescence of key components required to complete Warning Light Package options B358003000, B358203000, and D406601001, we will discontinue these effective immediately. We do have parts available to honor all current committed quotes however we will not be accepting any new orders configured with these selections. The chart below highlights the models impacted and we also provide a comparable warning light package to consider for your convenience. These comparable options operate similarly to what is being discontinued. You should consult with your customers to ensure any selected Warning Light package will fit their state requirements and vehicle needs.

| Discontinued Option | Comparable Option | Model   | Difference                                   |
|---------------------|-------------------|---------|--|
| D406601001          | D406601002        | C2      | No foot switch                               |
| B358003000          | B358004000        | DRW/SRW | No foot switch                               |
| B358203000          | B358204000        | HDX/EFX | No foot switch                               |
| B358016000          | B358038000        | DRW/SRW | No toggle sw, Master sw. w/ amber activation |
| B358216000          | B358226000        | HDX/EFX | No override sw and no master sw              |

|  |   |   |
|--|---|---|
| <input checked="" type="checkbox"/> Saf-T-Liner C2 | <input checked="" type="checkbox"/> Saf-T-Liner HDX | <input checked="" type="checkbox"/> Saf-T-Liner EFX |
| <input checked="" type="checkbox"/> Minotour DRW   | <input checked="" type="checkbox"/> Minotour SRW    | <input type="checkbox"/> Minotrek                   |

