

The parts supply of LED marker lamps used in several applications for all products has been impacted significantly by the global electrical component pressure as well as COVID-related labor shortages in the country of origin. We are now forced to contain these part shortages by installing incandescent lamps in place of the selected LED lamps. The incandescent lamps are direct “plug and play” replacements and have the same fit form and function as the LED lamps.

This deviation began on 6/14/21 and is expected to continue through 7/31/21.

Our TBB supplier management team is working with the supplier to explore alternate paths to improve the impact timeline and resume deliveries of LED lamps as quickly as possible.

Please contact Jason Austin if you have questions: jason.austin@daimler.com

Roof mounted and side mounted directional / markers

Front and Rear ID Markers



IMPACTING ALL PRODUCTS.

<input checked="" type="checkbox"/> Saf-T-Liner C2	<input checked="" type="checkbox"/> Saf-T-Liner HDX	<input checked="" type="checkbox"/> Saf-T-Liner EFX
<input checked="" type="checkbox"/> Minotour DRW	<input checked="" type="checkbox"/> Minotour SRW	<input type="checkbox"/> Minotrek

