

REFERENCE:	Nova Bus Manuals
SECTION:	16: Electrical System
RS N°:	MQR 7621-2258
EFFECTIVE IN PROD.:	N/A

APPLICATION DEADLINE: 2022JL15  
CLAIM REFERENCE NUMBER: WB-5082

SUBJECT:	Actia "Brake Worn Out" telltale issue.
JUSTIFICATION:	The tell-tale light for the "Brake worn out" is actually non-fonctionnal.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	New Actia Software to be updated.	Nova Bus	Nova Bus	0.33 h
2	–	–	–	–

## MATERIAL

QTY	PART N°	REV.	DESCRIPTION	REPLACES PART N°
<b>LEVEL 1</b>				
1	N76216-16	–	PROGRAM DASH ACTIA GENERIC	–
<b>LEVEL 2</b>				
–	–	–	–	–

## DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED *	RETAINED	* Dispose of the unused parts and the defective parts in accordance with local environmental standards in effect.
	–	–	

## REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2021JN03	Initial release	Devanand

APPROVED BY:

Jean-Nicolas Fournier

Digitally signed by Jean-Nicolas Fournier  
DN: cn=Jean-Nicolas Fournier, o=Nova Bus, email=jean-nicolas.fournier@volvo.com, c=CA

PAGE 1 OF 3

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
Academy Busline - New Jersey	LC95	—	—	L82J2L9777559	L82J9L9777560	2
Academy Busline - New Jersey	LD60	—	—	L82JXM3752934	L82JXM3752948	15
Ann Arbor Area Transportation Authority Michigan - AAATA	LD05	2000	2000	L82J9L9777669	L82J9L9777669	1
Ann Arbor Area Transportation Authority Michigan - AAATA	LD09	2001	2007	L82J1M9777893	L82J2M9777899	7
Capital Area Transportation Authority Michigan - CATA	LD34	719	730	L82J8L9777730	L82J2L9777741	12
Capital Area Transportation Authority Michigan - CATA	LD35	6016	6018	S92J3L9777742	S92J7L9777744	3
CHARM city Baltimore - Maryland	LC73	1910218	1910223	L82J4K9777447	L82J8K9777452	6
CHARM city Baltimore - Maryland	LD37	1910234	1910239	L82JXL9777745	L82J3L9777750	6
Houston Texas - Metro	LC55	2070	2079	L82KXK9777378	L82K0K9777387	10
Houston Texas - Metro	LC91	2500	2501	L82J4L9777479	L82J0L9777480	2
Houston Texas - Metro	LC92	2502	2534	L82J8L9777601	L82J3L9777618	33
Montgomery County - Maryland	LC34	1946001D	1946015D	S92J4L9777474	S92J2L9777490	15
Montgomery County - North Carolina	LC33	194600	194600	S92J1K9777351	S92J1K9777351	1
Proto EPA 2021 ARTIC	LC75	—	—	S92J4K9777473	S92J4K9777473	1
Rochester New York - RTS	LB77	1902	1910	L82J4K9777352	L82J3K9777360	9
San Juan Puerto Rico	LD01	2020-01	2020-01	L82J0L9777561	L82J0L9777561	1
San Juan Puerto Rico	LD32	2021-01	2021-10	L82J5L9777751	L82J6L9777760	10

**WARNING**

---

FOLLOW YOUR INTERNAL SAFETY PROCEDURES.

## PROCEDURE

### REPROGRAMMING ACTIA SYSTEMS

This reprogramming procedure requires the use of the diagnostic and programming tool BASIC XS or CAT CAN. The choice of analyzer depends on the version of Windows installed. This tool is available from Prevost Parts at the customer's expense. For more information on this tool, contact Prevost Parts or your service representative. See section **16: 24-VOLT ELECTRICAL SYSTEM** of the Nova LFS maintenance manual for the programming procedure.

