

**DTC:** P0244-00**Bulletin:** RD21-037**Date:** July 15, 2021**Description:** Wastegate Stuck Close**Applies to:** US20 – US21 EmissionsFor Spanish click here: [ESPAÑOL](#)**General Information**

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P0244-00	Wastegate Stuck Close	None	None

Required Parts

Part Number	Description	Quantity
N/A	N/A	N/A

Repair Instructions

For US21-OBD20 Emissions Turbo-Compound Engines, during instances of low chassis air pressure the P024400 fault may occur due to a logic error.

For vehicles experiencing this fault, perform the following:

1. Allow air pressure to build fully - either by listening for the air compressor to shut off (along with the audible hiss from the dryer) or simply idling the truck for 10 minutes.
2. Switch the engine to the off position, wait 30 seconds and restart. At this point the monitor should then pass and heal the DTC.

If the fault remains after following the steps above follow GD and recommended actions for this DTC. This solution will be updated when new software has been released.

REMOTE DIAGNOSTICS REPAIR INSTRUCTIONS

**DTC:** P0244-00**Bulletin:** RD21-037**Date:** July 15, 2021**Additional Resources**

These repairs are the most likely fix for the identified fault, if this does not fix the issue, Tech Tool will need to be used for more detailed diagnostics. If filing a warranty claim, please include the ASIST case number.

Labor Code	
N/A	N/A
Causal Part	N/A

**DTC:** P0244-00**Boletín:** RD21-037**Fecha:** 15 de julio, 2021**Descripción:** Wastegate atascado cerrado**Se aplica a:** Emisiones de US20 – US21Para inglés, haga clic aquí: **ENGLISH****Información general**

Estas instrucciones de reparación están destinadas a abordar las siguientes fallas:

DTC	Descripción	Causa posible	Posibles síntomas (observados)
P0244-00	Wastegate atascado cerrado	Ninguna	Ninguna

Piezas necesarias

Número de pieza	Descripción	Cantidad
N/A		

Instrucciones de reparación

Para los motores turbo compuestos de emisiones US21-OB20, durante los casos de baja presión de aire del chasis, la falla P024400 puede ocurrir debido a un error lógico.

Para los vehículos que experimentan esta falla, realice lo siguiente:

1. Permita que la presión de aire se acumule completamente, ya sea escuchando que el compresor de aire se apague (junto con el silbido audible de la secadora) o simplemente dejando el camión en ralentí durante 10 minutos.
2. Ponga el motor en la posición de apagado, espere 30 segundos y vuelva a arrancar. En este punto, el monitor debería pasar y reparar el DTC.

Si la falla persiste después de seguir los pasos anteriores, siga GD y las acciones recomendadas para este DTC. Esta solución se actualizará cuando se lance un nuevo software.



DTC: P0244-00

Boletín: RD21-037

Fecha: 15 de julio, 2021

Recursos adicionales

Es muy probable que estas reparaciones solucionen la falla identificada; si esto no soluciona el problema, se requerirá el uso de Tech Tool para diagnósticos más detallados. Si presenta una reclamación de garantía, incluya el número de caso ASIST.

Código de trabajo	
N/A	N/A
Pieza causal	N/A