

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75479 - L663 20-21MY - Front Daytime Running Light(s) Are Not Working / Intermittent Operation

Models : Defender/L663

Engineer Chris Davies

Name :

Last Modified 19 JUL 2021 14:48:48

:

Category : Electrical

Symptom : 201000 Lighting Systems

Content : Issue:

JLR is investigating front Daytime Running Lights are not working or have an intermittent operation (see images attached).

Cause:

Unknown at this time.

Action:

Please carry out the following;

- Confirm the vehicle symptom as reported by the customer
- Highlight the DTCs and attach all the information identified plus the session file(s), photograph(s) and video(s) to an ePQR
- Please replace the affected headlamp with the applicable part from JLR EPC and hold onto the parts replaced, as engineering may request them to be returned for analysis.

Thank you in advance for your assistance with this matter.

File : [L663_DRL_Inop_Image.JPG](#)
[L663_DRL_Inop_Image_Close_Up.JPG](#)