

WMG4 Workshop campaign - Re-programming high-voltage charger (OBC)

Version 2

WMG4 Workshop campaign - Reprogramming high-voltage charger (OBC)

Overview

There is a possibility that the charging process may be restricted due to a software error in the 19.2 kW high-voltage charger (OBC).

To prevent this, the 19.2 kW high-voltage charger must be reprogrammed.

Please arrange for this measure to be carried out on the affected vehicles during the next workshop visit or before handing the vehicles over to customers.

Model type	Taycan (Y1A) Taycan Cross Turismo (Y1B)
Model year	2021
Number	1,048*

* Please note that vehicles that are currently in production will be added to this campaign every week. The affected manufacturing period and the number of vehicles may still change.

Parts required

No parts are required for carrying out the workshop campaign.

Required software

PIWIS Tester 3 test software version	40.350.035 (or higher)
--------------------------------------	------------------------

If other programming campaigns that affect the same control unit and involve the identical procedure are open for a vehicle in addition to this campaign, the affected control unit must only be programmed once using the current PIWIS Tester test software.

Please proceed as follows for the campaigns that have not been carried out:

- Mark the campaign as 'cannot be carried out' with the reason "Modification of the affected component" in PQIS. The "Warranty relevance" flag must be activated in order to be able to set a warranty claim and close the campaign.
- A warranty claim must be submitted for the campaign in which 0 TU is entered as the specified working time and no material items are specified.

Warranty processing

Validity:

This workshop campaign will be carried out up to 19.07.2026 and will be closed by the specified date. Please note that warranty claims can only be processed before this date.

Scope 1:

Damage code	WMG4 66 000
Repair code	1
Working time	75 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction	TI No. 110/21, Group 2, Service, WMG4
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information	See PCSS or Aftersales Document Database for reference

[WMG4 VIN List_Updated 7-27-21.xlsx](#) ⓘ

29.6 KB

(26 views)

Created by [Ryan Cooney](#) on Jul 26, 2021 3:32 PM. Last modified by [Ryan Cooney](#) on Jul 27, 2021 7:30 PM.

954 Views [Report Abuse](#)

Categories: Taycan, Workshop Campaigns

Tags : [reprogramming](#), [hv charger](#), [crossturismo](#), [taycan](#), [y1b](#), [wmg4](#), [t1a](#)

Content and Topics

Your Groups



Personal

Edit Profile



Manage

Admin Console



Create

Discussion



Your Content



Change Password



PPN Administration



Files



Your Places

Document

>

Collaboration >>

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)