

Technical Service Bulletin

91 MIB3: Audi connect installation does not complete

91 21 16 2061257/2 August 2, 2021. Supersedes Technical Service Bulletin Group 91 number 20-27 dated November 6, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4, S4, A4 allroad, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, A6, A6 allroad, A6 Avant, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q5, SQ5, Q7, SQ5, Q7, SQ5, Q7, SQ8, RS Q8, Audi e- tron uattro, and Audi e- tron Sportback	2021	All	MIB3	
Audi e-tron GT, Audi RS e-tron GT	2022	All	MIB3	

Condition

REVISION HISTORY					
Revision	Date	Purpose			
2	-	Revised header (Added Models)			
1	11/07/2020	Initial publication			

Customer states:

• The message "Audi connect installation: error during installation" is shown in the drop down menu of the MMI.

^{© 2021} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Technical Background

The installation of the Audi connect application in the MMI freezes due to a fault in the system.

Production Solution

Not applicable.

Service

- 1. Use the settings menu to reset the MMI to factory default settings and then restart the system.
- 2. Setup of the Audi connect functions starts again and should run until completed.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles.					
	G10 for CPO Covered Vehicles – Verify Owner.					
	• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.					
Service Number:	9196					
Damage Code:	0039					
Labor Operations:	Factory reset the MMI system	9196 9999	5 TU			
Diagnostic Time:	GFF	No allowance	0 TU			
	Road test prior to the service procedure	No allowance	0 TU			
	Road test after the service procedure	No allowance	0 TU			
Claim Comment:	As per TSB #2061257/2					

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2061257) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.