

Washer Fluid Low Message Displayed	18 - 21MY RR Velar
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>- A customer may report a washer fluid low message displays on the Instrument Panel Cluster (IPC), but the reservoir fluid level is not low.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>- Engineering is currently investigating this concern to understand root cause.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>- <b>SSM 75444</b> has been published to request an EPQR be submitted with specific test information to help support the investigation.</li> </ul>	