

Roof Opening Panel Inoperative

20 – 21MY Defender

Customer Voice:

- A customer may report that the roof opening panel does not operate or that the sunblind lost 'One Touch' operation.

Technical Description:

- This may be caused by the roof opening panel motor losing calibration.

Status:

- **SSM 75429** has been published to address this concern by providing repair guidance to calibrate the roof opening panel motor.
- The roof opening panel motor should not be replaced for this concern.

