
[Trouble viewing this email?](#)



Date: July 29, 2021
Attn: Service Department
Subject: Fast Charger Wire Harness

Dear GEM Dealer,

Please review the following communication that was posted on Thursday, 07/29/2021.

Some 2016-2021 GEM vehicles built with Fast Chargers (3 kW or 6 kW) may experience a premature failure to the charger itself, if a short circuit occurs on the vehicle.

To address this concern, GEM is releasing this Service Bulletin for dealers to replace the fast charger harness in all affected vehicles with a new harness that has a built-in fuse holder. Please refer to the instructions within this Bulletin.

Click [HERE](#) to view L-21-01 Service Bulletin

Click [HERE](#) to view L-21-01 FAQ

Thank you for your attention.

Sincerely,

Polaris Service

This email was sent by Polaris Inc. to

[Privacy Policy](#)

© 2021 Polaris Inc.

2100 Highway 55, Medina, MN 55340, USA | [Polaris.com](https://www.polaris.com)
