

**\* \* TECHNICAL INFORMATION NOTICE \* \***

**DATE:** July 23, 2021  
**TO:** Mitsubishi Motors US Service and Parts Managers  
**RE:** Wireless Phone Charger Inoperative  
**TIN NO.:** TIN-21-54A-002

.....

**AFFECTED VEHICLES:** 2022 Outlander

**PURPOSE:**

Should a 2022 Outlander come in for an inoperative Wireless Charger concern, please make sure to reference the applicable service manual diagnostic procedure for this type of incident. The wireless charger works with other systems and requires proper inspection and diagnosis before replacing the charger unit. There has been an increase in this type of repair where resetting the unit would have resolved the concern.

**Note: Wireless chargers replaced that are not defective are subject to verification.**

Please reference the attached Inspection Flowchart and Service Manual: Volume 4 > Power Supply, Ground & Circuit Elements Group 90 > Power Outlet for further diagnostic steps.

## Inspection Flowchart

