

**Subject: Engineering Information – Popping and/or Thump Type Noise Heard from Front Suspension During Sharp Turns and/or While Backing Out**

*This EI has been revised to end the need for information from the field. Please discard PIE0614.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2021	—	—	—	—
	CT5						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released March 02, 2021 May 28, 2021 – Ended the need for further information from the field.