

## **Service Bulletin**

Bulletin No.: 21-NA-137


Date: June, 2021

## **INFORMATION**

Subject: Information on Headlamp Beam Shadow Appearance and/or Driver Side to Passenger Side Beam Appears Unlevel

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Eligille.	iransinission.
Cadillac	CT4	2020	2021	_	_	All	All

Involved Region or Country	North America, Europe, Middle East, Cadillac Korea (South Korea), China
Condition	Some customers may comment on seeing a headlamp beam shadow appearance and/or the driver side beam may appear lower than the passenger side beam.



5844384

Cause



5844385

The cause of the condition may be that the shadow is the result of a design notch, which is NOT a defect, but a design intent to reduce distraction of oncoming traffic.

Correction

**Note:** If the customer concern appears the same as shown in the graphic examples above, this condition does NOT require adjustment or replacement of the lamp.

Please communicate to the customer that the headlamp system is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.

## **Parts Information**

No parts are required for this repair.

Version	1
Modified	Released June 14, 2021