

Subject: Engineering Information - Service Engine Soon Lamp Illuminated On Driver Information Center (DIC), DTC P208B Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

This PI has been revised to end the need for information from the field. Please discard PIE0602B.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2021	-	-	Equipped with 3.0L Engine (RPO LM2)	-
	Silverado 2500HD/3500HD					Equipped with 6.6L Engine (RPO L5P)	
GMC	Sierra 1500					Equipped with 3.0L Engine (RPO LM2)	
	Sierra 2500HD/3500HD					Equipped with 6.6L Engine (RPO L5P)	

If you encounter a vehicle with the above condition, refer to bulletin 21-NA-125 for further diagnosis.

Version	4
Modified	Released January 12, 2021 Revised February 11, 2021 – Revised to add 2020–2021 Silverado 1500 / Sierra 1500 and update the Correction. Revised March 29, 2021 – Revised to update the Cause, Correction and Contact Information. Revised June 02, 2021 – Ended the need for further information from the field.