

Subject: Engineering Information - Lane Keep Assist, Adaptive Cruise Control and/or Automatic High Beam Indicator is Inoperative, Forward Collision Alert Reduced Illuminated On Driver Information Center (DIC)

This PI has been revised to end the need for information from the field. Please discard PIE0619.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020	2021	-	-	-	-
Chevrolet	Trailblazer (VIN M)	2021		-	-	-	-

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released March 19, 2021 Revised June 15, 2021 – Ended the need for further information from the field.