



SIB 11 01 20

2021-06-02

B58C AND B58M ENGINES: ENGINE OIL FILTER INSERT IS DIFFICULT TO REMOVE – REMOVAL

MODEL

F22 (2 Series Coupe)	F23 (2 Series Convertible)	F30 (3 Series Sedan)	F32 (4 Series Coupe)
F33 (4 Series Convertible)	F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)	G01 (X3 Sports Activity Vehicle)
G02 (X4 Sports Activity Coupe)	G05 (X5 SAV)	G05 (X6 SAC)	G07 (X7 SAV)
G12 (7 Series Sedan)	G14 (8 Series Coupe)	G15 (8 Series Convertible)	G16 (8 Series Gran Coupe)
G20 (3 Series Sedan)	G29 (Z4 Roadster)	G30 (5 Series Sedan)	G32 (6 Series Gran Turismo)

All B58 engine variants

SITUATION

On rare occasions during an engine oil service, the BMW Original (Genuine) engine oil filter insert is either difficult to remove or breaks apart in the oil filter housing.

Please delete SI B11 01 20.

B11 03 21 replaces that SI.

Thanks

BMW Group

Michael J. Murray

Senior Product Engineer - Engine and Fuel Systems
Powertrain / Chassis Group – C4-US-A-61