

2020 Lxor

Furnace inop, fan will come on for less than a minute, and furnace never starts

Pulled furnace from unit to bench test . Found that cell (sail) Switch is not working properly not allowing furnace to fire up

Will need 1.0 to remove and replace cell switch. And .5 for diag

The time approved to help is 1.0 hour. Please contact Atwood/Dometic 800 825 4328 because warranty part and labor for the furnace will come directly from Atwood/Dometic.
The Authorization# 02062101 J for the work.